

Date: July 27, 2005

Technical Bulletin # TCH-013-010 Effective 7/18/2005 is posted on your web site.

This is for your information on how the OSP will document the results of the "Chuff" test.

During an annual or new bus inspection, if the "chuff" test does not perform as outlined in the Bendix service literature, then the bus will fail the inspection and will not be decaled for use. This is consistent with the zero defect policy currently in place.

During a spot inspection, if the "chuff" test does not perform as outlined in the Bendix Bulletin, then the defect will be noted but the bus will not be placed out of service.

A failed "Chuff" test will not be an "Out-of-Service" violation.

Lieutenant John P. Boster
Ohio State Highway Patrol
Office of Licensing and Commercial Standards
Motor Vehicle Inspection Unit
E-Mail - JPBoster@dps.state.oh.us
Phone 614-466-4056
Fax 614-752-0243